







HANDLEIDING MANUEL DE PRODUIT









A1	 ST4x12mm	X2
A2	 ST4x16mm	X4
A3	 St4x19mm	X4
A4	 ST4x30mm	X2
D1		X1
D2		X1
D3		X1
D4		X1
D5		X1
D6		X1
D7		X1

E1		X1
F1		X1
G1	 791mm	X1
G2	 793mm	X1
H1		X1
J		X1
J2		X2
K		X4
K1		X4
K3		X1
K4		X1




1 → 15




16 → 30


1



2












x1




2

1		x1
K1		x2
J		x1




3

4








x1


5



x1







4



5

J		X1	6		X1
K1		X1			




6






G2


793mm

x1



7






9


G1



791mm


x1





11

Φ 3.2mm



A3



St4x19mm


x4




K





x4



A3



K



12



A2





ST4x16mm

x4


J







x1



J



A2





13

H1









x1



H1


14


	D1  x1	E1  x1	F1  x1
	D2  x1	D3  x1	D4  x1
	D7  x1	D6  x1	D5  x1




15

	K3  x1	J2  x2
	K4  x1	A4  ST4x30mm x2
 $\Phi 6mm$ 		A1  ST4x12mm x2






2












x1




2

17

1		x1
K1		x2
J		x1




4









x1

5







x1





J		X1	6		X1
K1		X1			




21



G2




793mm

x1






3		x1
K1		x1
J		x1




G1




x1





26

 Φ 3.2mm		A3  St4x19mm	x4
	K 		x4



27



A2





ST4x16mm

x4


J







x1






J









A2








29

	D1  x1	E1  x1	F1  x1
	D2  x1	D3  x1	D4  x1
	D7  x1	D6  x1	D5  x1



	K3  x1	J2  x2
	K4  x1	A4  ST4x30mm x2
 $\Phi 6mm$ 		A1  ST4x12mm x2





CONDITIONS DE GARANTIE : Reportez-vous au livret de garantie Lapeyre, disponible aussi sur le site www.lapeyre.fr

LAPEYRE SA

Les miroirs, 18 avenue d'Alsace

92400 Courbevoie RCS Nanterre n°542 020 862

Service Clients : BP 149 93300 Aubervilliers Cedex